

## Explanation of issues related to FFP2 masks

Batch number HLB20200906W

On September 6, 2020, an OEM manufacturer produced a batch of FFP2 masks with batch number HLB20200906W (The product is shown in the picture below)



Due to the scarcity of raw materials, one of the suppliers provided a batch of melt blown which of the filtration rate did not meet the FFP2 standard. Both our company and the factory have discovered this problem, and in December 2020, we recalled the entire batch of masks with batch number HLB20200906W.

If you still have this batch of products, please contact us to arrange to return or exchange as soon as possible.

We attach great importance to the quality of masks. Most of our FFP2 masks have a built-in metal nose clip. We also have done CE certification with Dutch Notified Body BSI and German DEKRA certification. The current packaging of the product is the Dutch BSI (Notify Body NO. 2797) certified packaging.

We also applied for testing by TUV, and passed these tests

Thanks for your attention to IVROU. To prevent future problems from our products, we and the factory will strengthen production quality management better.

If you have more questions or suggestions, please feel free to contact us: [info@ivrou.com](mailto:info@ivrou.com)

UNIMAMA B.V.