

PRODUCT RECALL - TENDON MASTER PRO 9.2

14.3.2023

Lanex a.s. informs its customers that part of the manufactured climbing ropes TENDON Master Pro 9,2 mm, CS is recalled from the market as a precautionary measure.

This is due to the findings of a French independent testing laboratory, which measured fewer falls that rope can withstands than declared by the manufacturer. This is a total of 18 ropes.

In case you own the rope of the batch below, please write to us at: jiri.gazda@mytendon.com . We will contact you and replace the rope with a new one.

Identification of ropes for return:



Zakázka /batch	Product number	Product description
1602596	21112598	D092TP43C060C TENDONMasterPro;9,2-60m;C;CS;C03
1602608	21112598	D092TP43C050C TENDONMasterPro;9,2-50m;C;CS;C03
1612563	21113880	D092TP43C080C TENDONMasterPro;9,2-80m;C;CS;C03
1612569	21113880	D092TP43C060C TENDONMasterPro;9,2-60m;C;CS;C03
1613635	21114070	D092TP43C060C TENDONMasterPro;9,2-60m;C;CS;C03
1622593	21115143	D092TP43C050C TENDONMasterPro;9,2-50m;C;CS;C03
1622915	21115206	D092TP43C050C TENDONMasterPro;9,2-50m;C;CS;C03
1622916	21115206	D092TP43C060C TENDONMasterPro;9,2-60m;C;CS;C03
1623257	21115275	D092TP43C060C TENDONMasterPro;9,2-60m;C;CS;C03
1626971	21115816	D092TP43C060C TENDONMasterPro;9,2-60m;C;CS;C03
1623192	50016299	D092TP43C060C TENDONMasterPro;9,2-60m;C;CS;C03

All the information can be found on the label in the bottom right corner.

Thank you for your support and please accept our apologies for any inconvenience associated with this.